



Proper way to set excess brake line on reserve risers



Improper way to set excess brake line on reserve risers



1645 Lexington Avenue DeLand, FL 32724-2106 USA Telephone 386 736 7471 Fax 386 734 7537
www.uptvector.com
Rigging Loft rigging@uptvector.com